Date User: First Issue **Previous Run**

Friday, 30/11/2007 10:03:18 AM

Linda Lacelle

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services

Job Number : 36081 **Estimate Number** : 11004

: N/A P.O. Number

: 30/11/2007 This Issue Prsht Rev.

S.O. No. : MA

: SMALL /MED FAB

Written By **Checked & Approved By**

Comment

: Est.

98.11.26 Added Inspection DM Est Rev:E Now On Waterjet 07-03-22 JLM

Drawing Name

: CONSOLE BRACKET HI-SLOPE

: D2606 **Part Number**

Drawing Number Project Number : D2606 REV A1 : N/A

Drawing Revision

Material : 07/12/2007 **Due Date**

Qty: 10 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M2024T3S040

2024-T3 .040 sheet



Comment: Qty.:

0.1582 sf(s)/Unit Total:

1.5824 sf(s)

2024-T3 .040 sheet

Material: 2024-T3 (QQ-A-250/4) 0.040" thick

Stack of 10

(M2024T3S.040) Batch $\frac{104035}{103321} \times 3 = \frac{11074}{1074}$

1B07-12-5

2.0

WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D2606 Dwg Rev:_ A.\ Prog Rev:___/\(\frac{1}{2}\)

B 07-12-5



2-Deburr if necessary

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



HB 07-12-5



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK





10

Friday, 30/11/2007 10:03:18 AM Date: User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: CONSOLE BRACKET HI-SLOPE Job Number: 36081 Part Number: D2606 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 BRAKE NC NC BRAKE Comment: NC BRAKE Deburr 10 Form as per Dwg D2606 6.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 7.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Acid etch and Alodine as per QSI 005 4.1 8.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSIO Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 10.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE mi roorliste CL Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CH	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		· L					
Part No		PAR #· Fault Category:	NCP: Vos	N- DO	<u> </u>	Data	

QA: N/C Closed: _____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section I	Verification	Anneoval	Annroyal			
DATE	STEP	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	

				·						
							1			
						1				
-										

NOTE: Date & initial all entries

Dart Aerospace Ltd 😓 🔻

W/O:		WORK ORDER CH	IANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•		:					
Part No		PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:	

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	losed:	Date:

NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCR)			
DATE		Description of NC		Verification	Ammanual	A		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
								E
				, 				
		•						

NOTE: Date & initial all entries

DART AERO	SPACE LTD				Work Order:	
escription:					Part Number:	
spection Dwg	g: Rev:					Page 1 of 1
	·					raye i Oi i
	FIRST	ARTICLE IN	VSPECTION	ON CHE	CKLIST	
	X	First Artic	cle	Proto	type	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
890.	+ ,004 -,001	.100	æ			
.530	4010	.220	*			
.621	4- ,010	1621	*			
8,309	t/010	8,309	×			
015.8	4/017	8,710	X			
8.930	+/010	8.930	*			
1621	4010	,6H	*			
841	4, .010	,839	×			
1.589	4010	1,589	3 9			
1-869	+/_ (610	1.809	A			
2.430	1/ 1010	2.434	¥			
			·			
			ı			
						^
					,	
				-		
sured by: d	3 Aug	dited by: ර		Prot	otype Approval:	
	7-12-5	Date: of	11405		Date:	
	Change				Revised	hy Annroys
	New Issue				KJ/JLM	by Approved